

N0B-034

N0B-004

addition. Roof structure same. Six pane window, steep end up. New unit seems to be some kind of a living residence quarters. \_\_\_\_\_ corner notch or Hudson Bay corner. Drop siding south side of structure. Not sure whether frame or log under. New addition not peeled. West side of old structure double logged wall, sod inbetween, approximately, I take that back, looks like an additional Wanigan addition with a shorter gable.

Bob Bliss, \_\_\_\_\_, send a copy of management plan when prepared. General Delivery, Unalakleet.

Ungalik Roadhouse, cabin in ruin. Site with a cache probably a later period. Cache has evidence of fish nets, lead line, built with logs part, the bottom part. Top part built with plank wood, perhaps an older cache with a newer top. Log walls constructed with single dove-tailed corners. Hand blazed \_\_\_\_\_ inside to flatten wall surfaces, suspect possible wall covering inside. Main purlin to secondary purlins with G-poled roof, probably sod, evidence of galvanized tin laying around the structure. Fronts on an old bed, perhaps an old river bed \_\_\_\_\_ going through area.

N0B-063

Foothill Roadhouse in ruin. Established in 1920, ran until approximately 1931, called Eben Roadhouse. Previous roadhouse perhaps discussed by Goodwin was found on the beach in front of Bessum Slough. No evidence or remains of structure. I think we found Ebens as shown on map. \_\_\_\_\_ structure if, not even sure it is the structure however if it is there is evidence of pile of \_\_\_\_\_ ruins, deteriorated to the point that it is unable to definitely tell whether ruined or not. Unable to land due to thick undergrowth.

N0B-009

#### KOLTAG PORTAGE

Well, backside obviously in ruin. Nearly gone from river. Appears to have been a log structure. Saddle notched. Appears to have been a rough saddle notched. Chopped log ends. Spiked together, large spikes on side. Beers cans, recent. Schlitz and Budweiser. No chart made on this one. Presumed well backed corner monument has, lets see corners approximately 41 LKS north 6 degrees east, township S. 54, 54. Range, W. C or O-1, date 7/77. Evidence galvanized roofing along site, at site possibly corrugated galvanized roofing. Possible later use as a small smokehouse. Old wooden cabin directly off the mouth or off the end of the Old Woman Mountain. Probably would be gone within

N0B-034

the next year. One-half gone now, went out with spring breakup. Part of the cabin is downriver on a sandbar. One of the front, the front corner. Log structure half or dove-tailed, corner single dove-tail. Ruin structure. Doesn't appear that the cabin had been peeled when built. Entryway faces north directly on the river, on the creek coming from the old, coming from the southeast of Old Woman Mountain.

River littered with DEAD fish. Soon purlin ridge, G-poled roof, probably sod. No indication of galvanized roofing. Flooring unknown. Inside walls with bark unpeeled. Approximate size, 16 foot by 14 foot.

Old Woman, unable to land on site. Landed on sandbar across river. Unable to get directly onsite within 40 feet. Correction. Another cabin located at the Feeders Stream to the river of the cabin we assumed to be Old Woman, approximately 200 yards.

Structure standing without roof, caved in some, trees small poplar trees growing within the structure. Other structure lies with entryway pointing due west. Log structure assumed saddled notched corners, front entry to north or to west. No wall to the east. Appears possibly the inside logs on east were painted red. Appears to have been hand blazed.