SITE PRINCE CREEK MINE	AHRS	NO:	INHT NO:	
OTHER SITE NAMES:	TRAI	L SECTION: Seward-Rainy Pass Rainy Pass-Kaltag Kaltag-Nome	<u>*</u>)RY
LAND STATUS:		,		O
			A state of High Con-	
	4,			ENT
LEGAL DESCRIPTION:				
Approximate Actual X Quad. IDT 8-4 Township T26N Range 47 W Section /3 Subsection			•	INV
Latitude:				
UTM REFERENCE:				AII
Zone Easting LOCATION AND USE:	North	ing		N.
FIRST CREEK ABOVE WILL	OVO	CREEK		Œ
INSPECTED BY: PLETERSON	DATE:	JUNE 80 Aerial _	Onsite X	
	ing Co	River Com		А
WALLS: IN OUT FLOOR		ROOF	CORNER NOTCH	
Log-Rough Din		Sod Metal	Unknown	
Frame Oth	her	Wd. Plank		
Drop Siding Uni	known	Wd. Shingle Tar Paper		
Unknown		Unknown		
TREATMENT RECOMMENDED:	<u> </u>	ORDER OF SIGNIFICA	NCE:	
Site Protection		National		
Preservation/Stabilization Restoration Reconstruction Adaptive Reuse	on	Regional Local		
Estimated Treatment Costs	6.			

Estimated Planning/Research Costs

SITE	AHRS NO:	INHT NO:	
MANAGEMENT RATING CRITERIA ACCESS 40 POINTS			
5 Difficult (Dog Sled, Snow Mach., Heli.)			
20 X Medium			
(1 Day Hike, Boat, Fixed-Wing)			
40High			
(Auto/Road, Short Hike) CONDITION 40 POINTS			
Not Located			
1 × No Remains		- A	
3 Ruin	some wheal to	you stretus remain The other min with	
8 Poor (Roof In)	1 10	I una lega al origina	إسدا
15 Medium (Roof Intact) 25 Good (Maintained)	an care arrea	7/	•
25 Good (Maintained) 40 Restored	or may may	the olds mui up the	ند
PRESENT VISITOR USE	creck.	,	
Frequent			
X Infrequent			
None			
POTENTIAL VISITOR USE20 POINTS			
20 High			
10 Medium			

Orned by alin agloff rubose fathe "discovered" on Prince before he was born. The creek is still being nined. There are worth his father located I discovered on the creek, around 1910

- Epistin lane was built of agloff

REFERENCE: Par Laminutin aglest, Primer Creek, Jul 1780

SITE RECOMMENDATIONS:

5 X Low

Total Points Z6