Estimated Planning/Research Costs

SITE Pioneer Roadhouse #3	AHRS NO:	McG-009	INHT NO:
And the Control of th	And the second s	. Concern	
MANAGEMENT RATING CRITERIA			
ACCESS 40 POINTS			
5Difficult			
(Dog Sled, Snow Mach., Heli.)			
20 X Medium			
- (1 Day Hike, Boat, Fixed-Wing)			
40 High			
(Auto/Road, Short Hike)			•
CONDITION 40 POINTS			
Not Located			
1 No Remains			
3Ruin			
8x Poor (Roof In)			
15 Medium (Roof Intact)			
25 Good (Maintained)	A STATE		
40 Restored			
PRESENT VISITOR USE			
Frequent			
<u>x</u> Infrequent			•
None			
POTENTIAL VISITOR USE20 POINTS			
20 X High			. •
10 Medium			
5Low			the state of the s

220C

STATEMENT OF SIGNIFICANCE:

Total Points 48

Evidence that barn #3 served as a horse barn/storage shed in support of trail freighting.

REFERENCE:

SITE RECOMMENDATIONS:

- 1. Stabilize: Wood preservatives and brace existing log walls.
- 2: Include as part of a National Register nomination.
- 3. Nominate to the National Register.