

10 MILE ROADHOUSE

SITE BOSTON ROADHOUSE AHRS NO: RUB-005 INHT NO: _____

OTHER SITE NAMES:

BOSTON R.H. (MAY ~~BE~~ BE KNOWN AS THE BOSTON R.H. BY LOCALS IN LATER YEARS)

TRAIL SECTION:

Seward-Rainy Pass _____
 Rainy Pass-Kaltag X
 Kaltag-Nome _____

LAND STATUS: ADP 3/19/81 pm
VILLAGE SEL/W/D

LEGAL DESCRIPTION:

Approximate _____ Actual ✓
 Quad. RUBY C5
 Township 10S
 Range 17E
 Section 10
 Subsection SW 1/4

Latitude: 64° 41' 22"
 Longitude: 155° 29' 10"

UTM REFERENCE:

A _____
 Zone _____ Easting _____ Northing _____

LOCATION AND USE:

10 MILES FROM RUBY ON RUBY TO OPTIC TRAIL

INSPECTED BY: Peterson DATE: Jun 80 Aerial X Onsite _____

STRUCTURAL TYPE:

Shelter Structure X River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <u>X</u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <u>X</u>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u>X</u>	<u>X</u>		Unknown	<u>X</u>

TREATMENT RECOMMENDED:

- X LOCATE
- X Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse

ORDER OF SIGNIFICANCE:

- _____ National
- 1 Regional
- _____ Local

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
 Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 Medium
5 ___ Low

Total Points 51

STATEMENT OF SIGNIFICANCE:

Constructed in 1911, the roadhouse was approximately 10 miles from Ruby near Boston Dome. Significant because of its early association with the initial Gold activities in the Ruby District the Roadhouse ~~was short lived. The ~~house~~~~ operated for several years. The A.P.C. Annual Report of 1916 lists ~~the~~ it as a "stable" Roadhouse on the Ruby to Ophir trail.

REFERENCE:

Peru. Commissioner, Billy McLarty, Ruby, Aug 1980
Ruby Record Citizen, 1911. → 10's 10 mile Roadhouse
ARC 1916:
SITE RECOMMENDATIONS: