

SITE U.S. ARMY RELIEF TENT

AHRS NO: _____

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
 Rainy Pass-Kaltag X _____
 Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate X Actual _____
 Quad. OPH B-1 _____
 Township T24S _____
 Range R13E _____
 Section 21 OR 22 _____
 Subsection _____

Latitude: 63° 23' 30"
 Longitude: 156° 21' 00"

UTM REFERENCE:

A _____
 Zone Easting Northing

LOCATION AND USE:

LOCATED TO THE SOUTH OF DOMINION CREEK AND FORKS, APPROX 18 MILES FROM OPHIB

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse

- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

5 Difficult
(Dog Sled, Snow Mach., Heli.)

20 Medium
(1 Day Hike, Boat, Fixed-Wing)

40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

Not Located

1 No Remains

3 Ruin

8 Poor (Roof In)

15 Medium (Roof Intact)

25 Good (Maintained)

40 Restored

PRESENT VISITOR USE

Frequent

Infrequent

None

POTENTIAL VISITOR USE--20 POINTS

20 High

10 Medium

5 Low

Total Points 11

STATEMENT OF SIGNIFICANCE:

the U.S. Army constructed (4) tents on the Oplint to Poorman Summer Route in 1923. The tents served as relief ~~stations~~ ^{stations} for several years and were reported to be still standing in 1932.

REFERENCE:

AK. Road Commission Annual Report, 1936.

SITE RECOMMENDATIONS: