	IDT-031		
SITE Moore Creek Hallway Cabin	AHRS NO:	INHT NO: 260H	
OTHER CITE NAMEC.	TRAIL SECTION:		
OTHER SITE NAMES: Moore Creek Cabin	Seward-Rainy Pass	•	
			
Moore Creek Halfway	Rainy Pass-Kaltag		- Burgard
Support Cabin	Kaltag-Nome	On the Ass-Allere Statement Statement Commission Commis	
or to me to a land			O
LAND STATUS: 2/27/8/ pm State Patented 50-76-0149			NVENT
State Patented 50-76-0749	40		
•		*	
MTP 9/8/74		· · · · · · · · · · · · · · · · · · ·	
LEGAL DESCRIPTION: Approximate Actual X			
Quad. Iditarod B3 and B4	,		
Township 45 28 N. Range 45 44 W.			
Section 3/2		:	
Section 3634 Subsection NE4, SE4, SE4, SE4	1981		نــــــــــــــــــــــــــــــــــــــ
·			
Latitude: <u>63° 28' 23.59</u> ' Longitude: <u>157 31 2</u> 0			
Longitude: 157 31 20	405		
		<u>.</u>	
UTM REFERENCE:			
A	and make the second control of		AII
Zone Easting	Northing		N
LOCATION AND USE:			
Trapper's Cabin - Abandoned.			
		1	
THOROGED BY, I 1	DATE: 1978 Aerial	0	
INSPECTED BY: Lynch Peterson	DATE: 1978 Aerial	Onsite X	
STRUCTURAL TYPE: Shelter Structural Type:	· · · · · · · · · · · · · · · · · · ·	munity	
The state of the s	lng Community Oth		
Native Settlement Min.	ing community cen		
WALLS: IN OUT FLOOR	R ROOF	CORNER NOTCH	
Log-Rough X X Din		X Unknown	
Log-Hewn X Woo		Double Saddle	
		X	
The state of the s	mown Wd. Shingle		
Wall Covering	Tar Paper		
Unknown	Unknown		~
* Programme ** ** ** ** ** ** ** ** ** ** ** ** **	-	Controlled to the Controlled t	
TREATMENT RECOMMENDED:	ORDER OF SIGNIFICA	NCE:	
			ITAR
x Site Protection	National	•	
X Preservation/Stabilization	-		
Restoration	x Local		
Reconstruction			
Adaptive Reuse			.
-			
Estimated Treatment Costs			
Estimated Planning/Research Co	osts		

MANAGEMENT RATING CRITERIA			
ACCESS 40 POINTS			
5 X Difficult			
(Dog Sled, Snow Mach., Heli.)			
20 Medium			
(1 Day Hike, Boat, Fixed-Wing)			
40High			
(Auto/Road, Short Hike)			
CONDITION 40 POINTS			
Not Located			
1 No Remains			
3 Ruin			
8 Poor (Roof In)			
15 X Medium (Roof Intact)			
25 Good (Maintained)			
40 Restored			
PRESENT VISITOR USE			
Frequent			
X Infrequent			
None			
POTENTIAL VISITOR USE20 POINTS			
20 High			
10 Medium			
5 X Low			

Total Points 30

STATEMENT OF SIGNIFICANCE:

The Moore Creek Halfway Cabin was built in March 1939 as a relief cabin for Elmer Cuturie's Moore Creek Mine. Mining supplies were brought in from Flat to Moore Creek in the 1930s and 40s over the Bonanza Creek route of the Iditarod Trail. The Moore Creek Cabin was used as a halfway overnight stop by freighters and travelers.

REFERENCE:

Lynch, Alice J., 1979. A Preliminary Inventory of Cultural Resources of the Iditarod Trail Between Rainy Pass and Unalakleet. Bureau of Land Management. Oral Communication: Alvin Agloff, 1980. Prince Creek Mine (Palmer during winter) 50-year resident of area; father mined Prince Creek prior to Alvin. SITE RECOMMENDATIONS:

- 1. Stabilize existing structure (i.e., remove sod and repair roof, repair sash, install stove. For continued use as a support/survival cabin.
- 2. Record and remove artifacts from structure.