Estimated Planning/Research Costs

SITE Dalzell Roadhouse MANAGEMENT RATING CRITERIA ACCESS ---- 40 POINTS Difficult (Dog Sled, Snow Mach., Heli.) 20 X Medium (1 Day Hike, Boat, Fixed-Wing) High (Auto/Road, Short Hike) CONDITION ---- 40 POINTS Not Located No Remains Ruin 8 X Poor (Roof In) Medium (Roof Intact) Good (Maintained) 40 Restored PRESENT VISITOR USE Frequent X Infrequent POTENTIAL VISITOR USE--20 POINTS 20 High 10 X Medium 5 Low

STATEMENT OF SIGNIFICANCE:

Total Points 38

Available information suggests that the ruins at Dalzell are not those of the original roadhouse/relief cabin. However, existing information suggests that the immediate area served as the location for several cabins/roadhouses from 1910 to 1930.

AHRS NO: McG-003

INHT NO: 220A

The existing cabin site possesses a commanding view of the Dalzell Creek drainage and the headwaters of Pass Creek.

REF:

Oral communication with the people of Nicholai indicates a long traditional use of Rainy Pass.

CAPWALLADER, 1917, IDS AS ROINY PASS ROSOIHOUSE "OPERATED BY CLAUS ANDERSON A.R.C. MAP OF ALASKA, 1939 ID'S THE "PALZELL S.C."

REFERENCE: MCPHERSON'S SURVEY, DEC, 1914 - 10'S AS "RAINY PASS ROAD HOUSE" Personal Informants:

Nick Dennis, Nicholai (guided at Dalzell for 15 years).

Misko Dephone, Nicholai.

Bill Schneider, NPS, Anthropologist for Denali (Continued on next page) SITE RECOMMENDATIONS:

- Continued site protection from fire/vandalism.
- Stabilization to prolong ruins (i.e. wood treatment, wall bracing and signing).
- Reconstruction of a reflief/shelter cabin in support of anticipated recreational activities.
- Nominate to the National Register.