

Old St. Nicholas Russian Orthodox Church

ANC-024

SITE GREEK MISSION AHRS NO: ANC-022 INHT NO: _____

OTHER SITE NAMES:

EKLUTNA RUSSIAN-GREEK
ORTHODOX MISSION / CHURCH.
- INDIAN VILLAGE -

TRAIL SECTION:

Seward-Rainy Pass X
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. ANC.
Township T16N
Range R1W
Section 24
Subsection SE 1/4, NE 1/4, SE 1/4, SE 1/4, NE 1/4 ^{CAMP}

Latitude: 61° 22' 35"
Longitude: 149° 20' 40"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- ___ Frequent
- ___ Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 ___ Medium
- 5 ___ Low

Total Points 100

STATEMENT OF SIGNIFICANCE:

PLAT REFERS TO AS GR. MISS, TR A — GRUSK MISSION, TRIGLA A ^{SURVEY}

REFERENCE:

GEN. LAND OFFICE PLAT, JUNE 25, 1914, DAVIDSON, —> LOCATES BY NAME
AK CENTRAL R.R. MAP, NOV 19, 1906, POLAND —> ID'S INDIAN VILLAGE W/ 3 CABINS

SITE RECOMMENDATIONS: