WATSON'S ROADHOUSE

SITE BROWN'S POADHOUGE	AHRS NO:	<u>IN</u>	HT NO:	k
OTHER SITE NAMES:	Rain	TION: ord-Rainy Pass y Pass-Kaltag ag-Nome	<u> </u>)RY
LAND STATUS:				
				ENT
LEGAL DESCRIPTION: Approximate Quad. Township Range Section Subsection NW4, NEV4, S				INVE
Latitude: 60° 27' 55" Longitude: 149° 70' 40"	_	•		J
UTM REFERENCE: A Zone Easting	Northing			AII
NW SIDE OF THE RADIO TOU MAY BE ON ORIGIONAL SIT	uers (4) e Ce	agt of eklutn	ia, towers	百
INSPECTED BY:	DATE:	Aerial	Onsite	_ [-
Native Settlement		River Commun	iity	_ A
WALLS: IN OUT FI Log-Rough Log-Hewn Frame Drop Siding Wall Covering Unknown	Dirt Wood Other Unknown	ROOF Sod Metal Wd. Plank Wd. Shingle Tar Paper Unknown	CORNER NOTCH Unknown	ITARO
TREATMENT RECOMMENDED:	ORDER	OF SIGNIFICANCE	:	_ [-1
Site Protection Preservation/Stabiliza Restoration Reconstruction Adaptive Reuse	ation	National Regional Local		IDI
Estimated Treatment Costs Estimated Planning/Research	Costs			

SITE	AHRS NO:	INHT NO:
MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS		
5 Difficult		
(Dog Sled, Snow Mach., Heli.)		
20 Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 × High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
× Not Located		
1 No Remains		
3 Ruin		
8 Poor (Roof In)		
15 Medium (Roof Intact)		
25 Good (Maintained)		•
40 Restored		
PRESENT VISITOR USE		
Frequent		
<u>∨</u> Infrequent		
None		
POTENTIAL VISITOR USE20 POINTS		•
20 × High		
10 Medium		
5Low		
Total Points 60		
Total Points		

STATEMENT OF SIGNIFICANCE:

SITE LOCATED ON LYINDH W. TURNER HOMESTEAD (8.9-17) #03746

REFERENCE:

GEN. LAND OFFICE PLAT, JUNE 86,1914, DAVIDSON, -> 10'S P.H., A BARN AND A HOUSE

SITE RECOMMENDATIONS: