SITE F. HUNTS LABIN	AHRS NO:		INHT NO:	k.
OTHER SITE NAMES:	Rainy	TION: rd-Rainy Pass y Pass-Kaltag ag-Nome	<u>x</u>)RY
LAND STATUS:	_		V 4	0 1
				ENT
LEGAL DESCRIPTION: Approximate Actual X Quad. ANC A-8 Township TIGN Range RIW Section 24 Subsection NE 4, NW 4, NW	- - -			INVE
Latitude: 61° 78'05" Longitude: 149° 12'05" UTM REFERENCE: A Zone Easting LOCATION AND USE: NORTH OF TIZALL ± 1/2 MIL	Northing	L DEM BLOF	F.	RAIL
INSPECTED BY:	DATE:	Aerial	Onsite	F
STRUCTURAL TYPE: Shelter St Native Settlement Mi	ructure ning Communi	River Comm		_ A
Log-Hewn W Frame 0	OR I	ROOF Sod Metal Wd. Plank Wd. Shingle Tar Paper Unknown	CORNER NO Unknown	
TREATMENT RECOMMENDED:	ORDER	OF SIGNIFICAN	CE:	
Site Protection Preservation/Stabilizat Restoration Reconstruction Adaptive Reuse	ion -	National Regional Local		10
Estimated Treatment Costs Estimated Planning/Research	Costs			

SITE	AHRS NO:	INHT N
MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS		
5 Difficult	•	
(Dog Sled, Snow Mach., Heli.)		
20 X Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located		
1 X No Remains		
3Ruin		
8Poor (Roof In)		
15 Medium (Roof Intact)		
25Good (Maintained)		
40Restored		
PRESENT VISITOR USE		
Frequent		
<u> </u> Infrequent		
None		
POTENTIAL VISITOR USE20 POINTS		
20 High		

STATEMENT OF SIGNIFICANCE:

Total Points 26

10 Medium
5 X Low

ASSUMED CABIN RESIDENCE - QUEN ITS LOCATION ON KNIK ARM HIS PROBABLY ECOPED INTO OCEAN.

REFERENCE:

GEN . LAND OFFICE PLAT, JUNE 25,1914, DAVIDSON - LOCATES

SITE RECOMMENDATIONS: