

SITE Summit Roadhouse AHRS NO: 10T-044 INHT NO: \_\_\_\_\_

OTHER SITE NAMES:

Summit Relief Cabin

TRAIL SECTION:

Seward-Rainy Pass \_\_\_\_\_  
Rainy Pass-Kaltag X  
Kaltag-Nome \_\_\_\_\_

LAND STATUS: 2/13/81 pm

STATE PATENTED # 50-76-0149

(MTP 9-9-76)

LEGAL DESCRIPTION:

Approximate \_\_\_\_\_ Actual X  
Quad. Iditarod B-5  
Township 28 N.  
Range 47 W.  
Section 30  
Subsection NE

Latitude: \_\_\_\_\_  
Longitude: \_\_\_\_\_

UTM REFERENCE:

A \_\_\_\_\_  
Zone \_\_\_\_\_ Easting \_\_\_\_\_ Northing \_\_\_\_\_

LOCATION AND USE:

No remains. On summit between Flat and Iditarod.

INSPECTED BY: Peterson DATE: 1980 Aerial X Onsite \_\_\_\_\_

STRUCTURAL TYPE: Shelter Structure X River Community \_\_\_\_\_  
Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other \_\_\_\_\_

<u>WALLS:</u>	<u>IN</u>	<u>OUT</u>	<u>FLOOR</u>	<u>ROOF</u>	<u>CORNER NOTCH</u>
Log-Rough	_____	_____	Dirt	Sod	Unknown <u>X</u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <u>X</u>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u>X</u>	<u>X</u>		Unknown	<u>X</u>

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- X Site Protection
- \_\_\_\_\_ Preservation/Stabilization
- \_\_\_\_\_ Restoration
- \_\_\_\_\_ Reconstruction
- \_\_\_\_\_ Adaptive Reuse

- X National
- \_\_\_\_\_ Regional
- \_\_\_\_\_ Local

Estimated Treatment Costs \_\_\_\_\_

Estimated Planning/Research Costs \_\_\_\_\_

**IDITAROD TRAIL INVENTORY**

SITE Summit Roadhouse AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5     Difficult  
(Dog Sled, Snow Mach., Heli.)  
20 X Medium  
(1 Day Hike, Boat, Fixed-Wing)  
40     High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located  
1 X No Remains  
3     Ruin  
8     Poor (Roof In)  
15     Medium (Roof Intact)  
25     Good (Maintained)  
40     Restored

PRESENT VISITOR USE

- Frequent  
X Infrequent  
    None

POTENTIAL VISITOR USE--20 POINTS

- 20 X High  
10     Medium  
5     Low

Total Points 41

STATEMENT OF SIGNIFICANCE:

Reported relief cabin at the summit between Iditarod and Flat. Cabin used by the many "foot" travelers between the two communities ~~AND~~ ~~TO~~ PROVIDE MEALS AND DRINK. OVERNITE LODGING DID NOT PLAY A SIGNIFICANT PART IN ITS USE.

REPORTED TO HAVE BEEN A LARGE 2 STORY LONG STRUCTURE ON THE TRAIL AND ON THE TRAMWAY BETWEEN IDITAROD & FLAT. 2 DIFFERENT LOCATIONS ~~WAS~~ ~~HAVE~~ WERE ~~BEING~~ USED. #1 - ~~WINTER~~ ALONG THE WINTER TRAIL  
#2 - ALONG THE TRAMWAY WHICH OPERATED FROM BREAKUP TO FREEZE-UP.

REFERENCE:

PERSONAL COMMUNICATION: TOMMY GULORSTIE, 1980, <sup>AND</sup> V. DONNA McALPINE, 1980  
IDITAROD PIONEER, 1910-11.

SITE RECOMMENDATIONS:

1. Continue historic research to verify exact location and type of structure.  
Explore photo resources.