

SITE Summit Relief Cabin

AHRS NO: IDT

INHT NO: _____

OTHER SITE NAMES:

Summit Cabin
ARC Relief Cabin
FOOT OF SUMMIT ROADHOUSE - 1911
BARLOW CABIN? (A.R.C. 1936)

TRAIL SECTION:

Seward-Rainy Pass
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: 2/13/81
State Patented

ADP 4/8/81

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. Iditarod C3
Township 28 N.
Range 43
Section 12
Subsection SW

IDT
T 28N
R 49W
13
NW 1/4, NE 1/4, NE 1/4

Latitude: 62 31' 40"
Longitude: 157 20' 50"
21' 05"

UTM REFERENCE:

A
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

Abandoned. - RUIN.

± 1/2 MILES SOUTH OF CAMELBACK MOUNTAIN ON HEADWATERS OF BONANZA CR.

INSPECTED BY: Peterson DATE: 1980 Aerial X Onsite _____

STRUCTURAL TYPE:

Shelter Structure X River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	<u>X</u>	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood _____	Metal _____	Double Saddle _____
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown <u>X</u>	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	<u>X</u>	_____		Unknown _____	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

X Site Protection
_____ Preservation/Stabilization
_____ Restoration
_____ Reconstruction
_____ Adaptive Reuse

_____ National
_____ Regional
X Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE Summit Relief Cabin

AHRS NO: 021

~~IDT-011~~

INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 13

STATEMENT OF SIGNIFICANCE:

Goodwin, in his 1910-11 survey, first mentions the existence of a Summit Roadhouse. The structure, because of its size and ARC record, was more of a relief cabin located near the summit of Camelback Pass. Records show that the log structure received a metal roof in 1931. Aerial reconnaissance pinpointed the ruin in 1980.

REFERENCE:

Lynch, Alice J., 1979. A Preliminary Inventory of Cultural Resources of the Iditarod Trail Between Rainy Pass and Unalakleet. Bureau of Land Management.

IDITAROD PIONEER-1911, REFERS TO A "FOOT OF SUMMIT ROADHOUSE"
A.E.C. McPHERSON SURVEY, DEC 1914 --> LOCATES A CABIN IN VICINITY OF THE RELIEF CABIN

SITE RECOMMENDATIONS:

1. Include as part of the trail archeological test program.