

SITE SLOW FORK VILLAGE AHRS NO: MED-020 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate X? Actual
Quad. MED A-2 A-1
Township R 26 S
Range R 28 E
Section 32 - 29
Subsection _____

Latitude: _____
Longitude: _____

UTM REFERENCE:

A _____
Zone Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	___	Dirt	Sod	Unknown
Log-Hewn	___	___	Wood	Metal	___
Frame	___	___	Other	Wd. Plank	___
Drop Siding	___	___	Unknown	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	___	___		Unknown	___

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- ___ Site Protection
- ___ Preservation/Stabilization
- ___ Restoration
- ___ Reconstruction
- ___ Adaptive Reuse
- ___ National
- ___ Regional
- ___ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 11

STATEMENT OF SIGNIFICANCE:

REFERENCE:

BILL SMYDER, PERS. COMMUNICATION, 1980

SITE RECOMMENDATIONS: