

SITE DREDFE - GANES CR

AHRS NO: _____

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. 4PH 42
Township T28S
Range R13E
Section 5
Subsection SW 1/4, NE 1/4, NE 1/4
Latitude: 102° 05' 28"
Longitude: 156° 26' 00"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: PERSON

DATE: Aug 81

Aerial X Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other gold DREDFE

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	___	Dirt	Sod	Unknown
Log-Hewn	___	___	Wood	Metal	___
Frame	___	___	Other	Wd. Plank	___
Drop Siding	___	___	Unknown	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	___	___		Unknown	___

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- X Site Protection
- X Preservation/Stabilization
- ___ Restoration
- ___ Reconstruction
- ___ Adaptive Reuse

- ___ National
- ___ Regional
- ___ Local

Estimated Treatment Costs _____

Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
1 ___ No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
___ Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 Medium
5 ___ Low

Total Points 65

STATEMENT OF SIGNIFICANCE:

DREDGE WAS ORIGINALLY ON GREENSTONE CREEK BY POORMAN(?) AND MOVED TO GANES CR. IN 1923 - H. MISLOVICH

REFERENCE:

PERSONAL COMMUNICATION, HOWARD MISLOVICH. NOV. 1980

SITE RECOMMENDATIONS: