

SITE GANES CREEK AHRS NO: OPH-001 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: 2/27/81 pm
F 11902 offsite out SP PLO-5184
Sec 50m AA 21375/55
AA 8103-11 / reg Set aplm

ADP 3/19/81
VILLAGE W/D
MINERAL SURVEY APLN
PLACER CLAIMS - MAGNUSON & TAKOTNA
VILLAGE SET WARDEN

INTP 5-30-79

LEGAL DESCRIPTION:

Approximate Actual _____
Quad. OPH A-1
Township 28 S
Range 13 E
Section 5
Subsection _____

Latitude: 63° 05' 20"
Longitude: 156° 26' 00"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
 - 1 No Remains
 - 3 Ruin
 - 8 Poor (Roof In)
 - 15 Medium (Roof Intact)
 - 25 Good (Maintained)
 - 40 Restored
- } SEVERAL STRUCTURES REMAIN

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 65

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: