

Iditarod National Historic Trail Office
Bureau of Land Management

General Work Sheet

Name of Site	AHRS Number	Site Number
--------------	-------------	-------------

Other Site Names or Location

BROWN C.R. LOCATION

Land Status

UTM Coordinates (zone, easting, northing)	Title of USGS Quadrangle	Geographic Location
--	--------------------------	---------------------

Present Owner's Name and Address

UNKN

Present Occupant

Present Use

RUIN

Brief Statement of Significance:

Project Information

Type of Inspection

On Site X JULY 13, 80

Aerial

Name of Site	Site Number
--------------	-------------

PHYSICAL HISTORY

Dates of Erection

Architect

Original and Subsequent Owners

Builder or Contractor, Suppliers

Notes on Original Plan and Construction of Building

Notes on Known Alterations and Additions, with Dates and Architects

HISTORICAL EVENTS AND PERSONS ASSOCIATED WITH THE BUILDING

SOURCES OF INFORMATION

Primary and Unpublished Sources

Secondary and Published Sources

Likely Sources Not Yet Investigated

Prepared by

Date of Visit

Weather Conditions

Iditarod National Historic Trail

Inventory Work Sheet

Site Name BROWN CR (LOCATION)	AHRS Number	Site Number
----------------------------------	-------------	-------------

Trail Section HUNTER TRAIL	Distance From _____, _____ Miles or Flight Time
-------------------------------	--

Land Status

Location BROWN CR.	USGS Map Quad
-----------------------	---------------

Longitude	Latitude
-----------	----------

LEGAL DESCRIPTION

Township	Range	Sec.	Sub.	Meridian
----------	-------	------	------	----------

Acreage

GENERAL DESCRIPTION

Architectural Merit and Interest

OLD - POSS R.H. SITE

Condition of Fabric

RUIN - BEYOND SALVAGE,

SITS IN BOG

DETAILED DESCRIPTION OF EXTERIOR

Overall Dimensions	Number of Bays 1	Number of Stories 1	Layout, Shape 
--------------------	---------------------	------------------------	--

Foundations

LOG ON GRADE

Wall Construction, Finish and Color

INTERIOR - UNKNOWN

EXTERIOR.

Structural System, Framing

LOG - $\pm 8'$ - ~~ROUGH~~ ROUGH SADDLE NOTCH.

CHOPPED & NOTCHED ENDS

Porches, Stoops, Bulkheads

UNKNOWN

Windows

UNKNOWN

Openings: Doorways and Doors

1 ENTRY DOOR

Windows and Shutters

1 WINDOW

FACING ——— MOUNTAIN

Roof: Shape, Covering

ASSUMED GABLE

MOSS ON CEDAR POLES

Cornice, Eaves

UNKNOWN


Dormers, Cupolas, Towers

UNKNOWN

±11" PINE (RIDGE)

DETAILED DESCRIPTION OF INTERIOR

Floor Plans (by floors)



Stairways

NONE.

Flooring

UNKN.

Wall and Ceiling Finish

UNKN

Corways and Doors

1 DOOR.

Special Decorative Features, Trim and Cabinet Work

UNKN.

Notable Hardware


NONE

BLOOD CAN, MILK CANS

Mechanical Equipment (Heating, Lighting and Plumbing Systems and Fixtures of Note)

SITE AND SURROUNDINGS

General Setting (Including Orientation by Compass Reading)



Historic Landscape Design

Outbuildings

NO STRUCTURES, OR RUINS EVIDENT.

Site Use Recommendations

POSS PALE SUPPORT SITE (NEW COND)

Proposed Site Preservation Program and Cost Estimate

Prepared By

[Handwritten signature]

Date

4/13/80