

SITE BROWN CREEK SHELTER CABIN AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass

Rainy Pass-Kaltag X

Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. OPH
Township T28S
Range R10E
Section 24
Subsection SE 1/4, SE 1/4

Latitude: 63° 02' 35"

Longitude: 156° 42' 00"

UTM REFERENCE: _____

A _____

Zone _____ Easting _____

Northing _____

LOCATION AND USE:

ON BROWN CREEK, BETWEEN MCCARTHY R.H. & HUNTER TRAIL BRING, 13 MILES
FROM SHERANBERS 1160 WY ROADHOUSE

INSPECTED BY: PETERSON

DATE: AUG 81

Aerial _____

Onsite X

STRUCTURAL TYPE:

Shelter Structure X

River Community _____

Native Settlement _____

Mining Community _____

Other _____

WALLS:

IN

OUT

FLOOR

ROOF

CORNER NOTCH

Log-Rough _____

Dirt _____

Sod _____

Unknown _____

Log-Hewn _____

Wood X

Metal X

Frame X

Other _____

Wd. Plank _____

Drop Siding _____

Unknown _____

Wd. Shingle _____

Wall Covering _____

Tar Paper _____

Unknown _____

Unknown _____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

X Site Protection
X Preservation/Stabilization
_____ Restoration
_____ Reconstruction
_____ Adaptive Reuse

_____ National
_____ Regional
_____ Local

Estimated Treatment Costs _____

Estimated Planning/Research Costs _____

IDENTIFIED TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ☐ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ☒ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 ☐ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ☐ Not Located
1 ☐ No Remains
3 ☐ Ruin
8 ☐ Poor (Roof In)
15 ☒ Medium (Roof Intact)
25 ☐ Good (Maintained)
40 ☐ Restored

PRESENT VISITOR USE

- ☐ Frequent
☒ Infrequent
☐ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ☐ High
10 ☒ Medium
5 ☐ Low

Total Points 45

STATEMENT OF SIGNIFICANCE:

AK. ROAD COMMISSION CABIN, CONSTRUCTED IN 1923 ALONG WITH THE "FIRST CLASS" RELIEF CABIN ON THE HUNTER TRAIL (FROM OPIHIE TO ~~10120~~ SHERMAN'S HALF WAY P.H.

TYPICAL OF THE FRAME STRUCTURE BUILT BY THE ROAD COMMISSION.

REFERENCE:

ALASKA ROAD COMMISSION ANNUAL REPORT, 1923
A.B.L. AAP, 1936 → 10'S AS MAINTAINED SHELTER CABIN (S.C.)

SITE RECOMMENDATIONS:

REGIONS AS A SURVIVAL CABIN AND BASE SUPPORT FACILITY