

SITE MADISON CR. R.I.

AHRS NO: OPH-011

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. OPH
Township T 24 S
Range R 9 E
Section 22
Subsection NW 1/4

Latitude: 63° 23' 40"
Longitude: 157° 07' 00"

UTM REFERENCE:

A _____
Zone Easting _____ Northing _____

LOCATION AND USE:

AT CONFLUENCE OF MADISON CREEK AND TOLSON CREEK

INSPECTED BY: PETERSON

DATE: JUNE 8 Aerial X Onsite _____

STRUCTURAL TYPE:

Shelter Structure X River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <u>X</u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <u>X</u>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u>X</u>	<u>✓</u>		Unknown	<u>X</u>

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

_____ Site Protection
_____ Preservation/Stabilization
_____ Restoration
_____ Reconstruction
_____ Adaptive Reuse

_____ National
_____ Regional
_____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDENTIFIED TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 13.

STATEMENT OF SIGNIFICANCE:

SHORT LIVEN R.H. ON MADISON CREEK.

REFERENCE:

POULS, 1923, 324 10's A MADISON CR. R.H. NEAR DISAKAZAT.

SITE RECOMMENDATIONS: