

SITE Seward-Rainy Pass AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
 Seward-Rainy Pass _____
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____
 Kenai Peninsula Branch Trails

LAND STATUS: ADP 4/7/81
 OWNER: Reg Sel;
 USE: PLACE CUM

LEGAL DESCRIPTION:
 Approximate _____ Actual _____
 Quad. 251 0-6
 Township 7N
 Range 1E
 Section 26
 Subsection SE 1/4 NW 1/4
 Latitude: 60° 40' 30" N
 Longitude: 149° 17' 00" W

UTM REFERENCE:
 A 06 278 375 5728025
 Zone Easting Northing

LOCATION AND USE: was used as a temporary building site for a mining outfit

INSPECTED BY: J. MANTON DATE: _____ Aerial Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt _____	Sod _____	Unknown <input checked="" type="checkbox"/>
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown <input checked="" type="checkbox"/>	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown <input checked="" type="checkbox"/>	_____	_____		Unknown <input checked="" type="checkbox"/>	

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- Site Protection _____ National
- Preservation/Stabilization _____ Regional
- Restoration Local
- Reconstruction _____
- Adaptive Reuse _____
- Archeological Investigation _____
- Estimated Treatment Costs _____
- Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE Gleason's Cabin

AHRS NO: _____

INHT NO: 13094

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____

LAND STATUS: _____

Federal - USFS

LEGAL DESCRIPTION:

Approximate _____ Actual _____
 Quad. _____
 Township _____
 Range _____
 Section _____
 Subsection _____

Latitude: _____
 Longitude: _____

UTM REFERENCE:

A _____
 Zone _____ Easting _____ Northing _____

LOCATION AND USE:

Summit/Hope Military Road

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____

ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE Blowen s. Uluir AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- ___ Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 ___ Low

Total Points _____

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS:

USFS - No recommendation (10/10)