

IDITAROD TRAIL INVENTORY

SITE Chlukak AHRS NO: SOL-112 INHT NO: _____

OTHER SITE NAMES:

Chekokook
Keokuk

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome X

LAND STATUS: ADP 4/7/81 pm
FLPMA; ST SEL; CEMETERY
VILLAGE SEL + W/O
REINDEER GRAZING

LEGAL DESCRIPTION:

Approximate	Actual	_____
Quad.	<u>SOL C3</u>	
Township	<u>11 S.</u>	
Range	<u>24 W.</u>	
Section	<u>24</u>	
Subsection	<u>SW SE SE SW</u>	

Latitude: _____
Longitude: _____

UTM REFERENCE:

A
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ **DATE:** _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ **ORDER OF SIGNIFICANCE:** _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

SITE Chiukak

AHRS NO: _____

INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points ~~45~~ 26

STATEMENT OF SIGNIFICANCE:

~~ARC Relief Cabin on site in good condition — ruins and parts of several other structures included behind. — Visual ARC feature is that a shelter and a barn are joined by a Day tent between.~~

REFERENCE:

SITE RECOMMENDATIONS:

Restore/repair for continued use.