

SITE MOUNTAIN CLIMBERS RH AHRS NO: TYO-022 INHT NO: _____

OTHER SITE NAMES:

HAYES RIVER ROADHOUSE
HALFWAY RH

TRAIL SECTION: (X)

Seward-Rainy Pass ✓
Rainy Pass-Kaltag
Kaltag-Nome

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate Actual X mp.
Quad. TYO-D5
Township T 22N
Range R 14W
Section ~~22~~ 22
Subsection ~~SE 1/4, NW 1/4, NW 1/4~~ SE 1/4 NW 1/4 SE 1/4.
Latitude: 61° 58' 50"
Longitude: 151° 48' 55"

UTM REFERENCE:

A

Zone _____ Easting _____ Northing _____

LOCATION AND USE:

NORTH SIDE OF SKWENTNA RIVER, 2 MILE WEST OF THE MOUTH OF HAYES RIVER, AND 1 MILE NORTH OF THE SKWENTNA RIVER. - June 1981. Smp. Pot.

INSPECTED BY: PETERSON DATE: June 81 Aerial X Onsite _____

STRUCTURAL TYPE:

Shelter Structure X River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	<u>X</u>	Dirt	Sod	Unknown <u>X</u>
Log-Hewn	___	___	Wood	Metal	<u> </u>
Frame	___	___	Other	Wd. Plank <u>X</u>	<u> </u>
Drop Siding	___	___	Unknown <u>X</u>	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	<u>X</u>	___		Unknown	___

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

___ Site Protection	___ National
___ Preservation/Stabilization	___ Regional
___ Restoration	___ Local
<u>X</u> Reconstruction Poss.	
___ Adaptive Reuse	

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ☐ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ☒ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 ☐ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ☐ Not Located
1 ☐ No Remains
3 ☐ Ruin
8 ☒ Poor (Roof In)
15 ☐ Medium (Roof Intact)
25 ☐ Good (Maintained)
40 ☐ Restored

PRESENT VISITOR USE

- ☐ Frequent
☒ Infrequent
☐ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ☐ High
10 ☒ Medium
5 ☐ Low

Total Points 38

STATEMENT OF SIGNIFICANCE:

Continuum Roadhouse from 1908 to 1919

REFERENCE:

SITE RECOMMENDATIONS: