

EVANS ISLAND, NE COAST
EV000 226-40-16582

2V007

22640 16557

IKTUA BAY

ASW
 PLOANADSCAT-90

ADF&G MULTI-ASSESSMENT DATA FORM

1 SURVEY TYPE: BS SS DS TS AVS SCHA MMHS PTA

2 REGION: PWS KP,CI K,AP

METHOD: Aerial Ground Boat

3 DATE: 4/11/90

15 HIGH TIDE TIMES: 1

21 TEAM RECORDER: R. Gustin

4 START TIME: 1020

16 HIGH TIDE HTS: 1

22 OBSERVERS: 1

5 STOP TIME: 1025

17 LOW TIDE TIMES: 1

23 AGENCY: ADFG HAB.

6 SEGMENT #: EU 007

18 LOW TIDE HTS: 1

24 PHOTOS TAKEN: Y (N)

7 STATION #:

19 TIDE HT AT SURVEY:

Roll #: Frame:

8 K-UNIT:

Ebb Slack Flood Slack

25 VIDEO TAKEN: Y (N) TAPE#:

9 STAT AREA:

20 USCG QUAD:

Start: End:

10 LAT:

11 LONG:

26 SAMPLES TAKEN? Y (N) Number

12 SOURCE: Map Loran

011

13 LOCATION: EVANS IS.

Sediment

14 DESCRIPTION: NE Coast

Biological

Water

EXTENT OF OIL

27 SURFACE COVERAGE

SHORELINE				STREAM			
L	W	M ²	%	L	W	M ²	%

36 CATALOGED ANAD. FISH STREAM? (Y) (N)

37 CATALOG #: 226-4057 ASW

38 STREAM NAME:

28 SURFACE THICKNESS

--	--	--	--	--	--	--	--

39 OIL IN STREAM BED? Y (N)

29 PENETRATION

40 OIL ON STREAM BANKS? Y (N)

30 OVERALL OIL IMPACT: N VL L M H

41 OIL ON BEACH ADJACENT TO MOUTH? (Y) (N)
 (within 50 meters)

31 OIL TYPE: Pooled Mousse Tar Asphalt Sticky Stain

42 OIL WITHIN 1 MILE OF STREAM? Y (N)

32 OILED DEBRIS? Y N

Where:

33 SHORELINE TYPE: Headland Low-lying Rocks Beach Cove
 Lagoon Marsh

43 ANADROMOUS FISH PRESENT? Y N

34 WAVE EXPOSURE: High Moderate Low

44 ANADROMOUS FISH OBSERVATION

35 SUBSTRATE TYPE: Bedrock Boulder Cobble

Gravel Sand Mud/silt

Species	Aerial	Ground


COMMENTS: NO OIL NOTED

NO sketch AW 10/8/91

ACE 7237704+15

EV007

500.0



very heavy

OILING

H - Heavy
M - Moderate
L - Light
VL - Very Light
N - None
NS - Not Surveyed

Distance In Meters

ACE 7237712-1L/AR/FF



ANADSCAT-90

ADF&G MULTI-ASSESSMENT DATA FORM

1 SURVEY TYPE: BS SS DS TS AVS SCHA MMS PTA2 REGION: PWS KP,CI K,APMETHOD: Aerial Ground Boat3 DATE: 4/11/9015 HIGH TIDE TIMES: 121 TEAM RECORDER: R. Gusten4 START TIME: 102016 HIGH TIDE HTS: 122 OBSERVERS: 15 STOP TIME: 102517 LOW TIDE TIMES: 123 AGENCY: ADF&G HAB.6 SEGMENT #: EU 00718 LOW TIDE HTS: 124 PHOTOS TAKEN: Y (N)

7 STATION #:

19 TIDE HT AT SURVEY:

Roll #: Frame:

8 K-UNIT:

Ebb Slack Flood Slack

25 VIDEO TAKEN: Y (N) TAPE#:

9 STAT AREA:

20 USCG QUAD:

Start: End:

10 LAT:

11 LONG:

26 SAMPLES TAKEN? Y (N) Number12 SOURCE: Map Loran13 LOCATION: EVANS IS.14 DESCRIPTION: NE Coast

Oil

Sediment

Biological

Water

EXTENT OF OIL

36 CATALOGED ANAD. FISH STREAM? Y (N)37 CATALOG #: 226-4057 ATW

38 STREAM NAME:

39 OIL IN STREAM BED? Y (N)40 OIL ON STREAM BANKS? Y (N)41 OIL ON BEACH ADJACENT TO MOUTH? Y (N)
(within 50 meters)42 OIL WITHIN 1 MILE OF STREAM? Y (N)

Where:

43 ANADROMOUS FISH PRESENT? Y (N)44 ANADROMOUS FISH OBSERVATION
Species Aerial Ground

27 SURFACE COVERAGE

28 SURFACE THICKNESS

29 PENETRATION

30 OVERALL OIL IMPACT: N VL L M H

31 OIL TYPE: Pooled Mousse Tar Asphalt Sticky Stain

32 OILED DEBRIS? Y N

33 SHORELINE TYPE: Headland Low-lying Rocks Beach Cove
Lagoon Marsh

34 WAVE EXPOSURE: High Moderate Low

35 SUBSTRATE TYPE: Bedrock Boulder Cobble


Gravel Sand Mud/silt

COMMENTS: NO OIL NOTED

ACE 7237704+15

DESCRIPTION

48 OIL DISTRIBUTION DIAGRAM



16559 4/13/90
TWC

24007

226-40-1655,

ADW

hole taken
to frame # and
direction.

ACE 7237705-1S



DATE PRINTED: 10/17/91

NON-DUCK STREAMS

PAGE 5

CATALOG NUMBER: 2264016557			SEGMENT#: EV007		LOCATION: EVANS ISLAND, IKTUA BAY			SEQ:
DATE	SURVEY	SITE	W x L (m) SITE TYPE	PERCENT OIL	THICKNESS & PENETR. (cm)	OIL TYPES, DEPTH INTERVAL(cm)	SITE SPECIFIC COMMENTS	
04/11/90	PRE-ANADS CAT	Ø				NO OIL	NO OIL FOUND.	
MAD vs. OG: COMMENTS: NO OIL NOTED.								