

SITE WHITE'S CABIN AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass x
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual x
Quad. ANC B-8
Township T16N
Range R3W
Section 24
Subsection SW $\frac{1}{4}$, SW $\frac{1}{4}$, NW $\frac{1}{4}$

Latitude: 61° 27' 30"
Longitude: 149° 34' 20"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

CABIN LOCATED ON WHITE'S HOMESTEAD # 02764, 12-13-1915. \pm 1 MILE WEST FROM KENNIC TOWNSITE, \pm $\frac{1}{8}$ MILE SOUTH OF TRAIL

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

_____ Site Protection	_____ National
_____ Preservation/Stabilization	_____ Regional
_____ Restoration	_____ Local
_____ Reconstruction	
_____ Adaptive Reuse	

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDENTIFIED TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ☐ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ☒ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 ☒ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ☐ Not Located
1 ☐ No Remains
3 ☐ Ruin
8 ☒ Poor (Roof In) - Per Joe Redington
15 ☐ Medium (Roof Intact)
25 ☐ Good (Maintained)
40 ☐ Restored

PRESENT VISITOR USE

- ☐ Frequent
☒ Infrequent
☐ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ☒ High
10 ☐ Medium
5 ☐ Low

Total Points ~~68~~ 58

STATEMENT OF SIGNIFICANCE:

This is a homestead cabin

REFERENCE:

GEN. LAND OFF. PLAT, OCT 24, 1914, DAVIDSON → LOCATES
(PERS. COMM) JOE REDINGTON SR, JUNE, 1986 → Repairs well built cabin complete with picket fences.

SITE RECOMMENDATIONS:

The cabin lies on the original old-timer trail and would offer an opportunity as part of a short (1) mile hike on the old-timer trail from Knike to White trail - for the visitor to Knike.