707-037

		01-03/		
SITE WANNIGAN, SWINGING DOME	AHRS NO: I	Dr-984 INH	T NO:	EL
OTHER SITE NAMES:	TRAIL SECT)RY
LAND STATUS: AD4 4/8/81 pm				ENTO
LEGAL DESCRIPTION: Approximate Actual Quad. IDT 6-5 Township 26 N Range 49 W Section 12 Subsection 5 5 5				INVE
Latitude: 62° 21' 12.96' Longitude: 158° 15' 56.64' UTM REFERENCE: A Zone Easting LOCATION AND USE:	Northing	· · · · · · · · · · · · · · · · · · ·		'RAII.
INSPECTED BY:	DATE:	Aerial	Onsite	E
STRUCTURAL TYPE: Shelter Stru Native Settlement Mini	cture ng Community	River Communi Other	ty	
WALLS: IN OUT FLOOR Log-Rough	t	Sod Metal Wd. Plank Wd. Shingle Tar Paper Unknown	Unknown	TARD
TREATMENT RECOMMENDED:	ORDER (OF SIGNIFICANCE:		
Site Protection Preservation/Stabilizatio Restoration Reconstruction Adaptive Reuse	on	National Regional Local		101
Estimated Treatment Costs Estimated Planning/Research Co	 sts			

MANAGEMENT RATING CRITERIA
ACCESS 40 POINTS
5 x Difficult
(Dog Sled, Snow Mach., Heli.)
20Medium
(1 Day Hike, Boat, Fixed-Wing)
40High
(Auto/Road, Short Hike)
CONDITION 40 POINTS
Not Located
1No Remains
3 ★ Ruin
8Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40Restored
PRESENT VISITOR USE
Frequent
<u></u>
None
POTENTIAL VISITOR USE20 POINTS
20High
10Medium
5 Low

Total Points 13

STATEMENT OF SIGNIFICANCE:

UNIKNOWN

REFERENCE:

SITE RECOMMENDATIONS: