

SITE WILLOW CR. ROADHOUSE AHRS NO: IDT-038 INHT NO: \_\_\_\_\_

OTHER SITE NAMES:  
KATE MASTER'S R.H.

TRAIL SECTION:  
Seward-Rainy Pass \_\_\_\_\_  
Rainy Pass-Kaltag X \_\_\_\_\_  
Kaltag-Nome \_\_\_\_\_

LAND STATUS:  
NOT ON SELECTION  
PRIVATE MINING CLAIMS OWNED BY THE FULLERTON BROTHERS.

LEGAL DESCRIPTION:  
Approximate X Actual \_\_\_\_\_  
Quad. IDT  
Township T26N  
Range R47W  
Section 6  
Subsection \_\_\_\_\_  
  
Latitude: 62° 22' 30"  
Longitude: 158° 04' 30"

UTM REFERENCE:  
A \_\_\_\_\_  
Zone Easting \_\_\_\_\_ Northing \_\_\_\_\_

LOCATION AND USE:  
EXACT LOCATION UNKNOWN - ACTIVE MINING

INSPECTED BY: PETERSON DATE: \_\_\_\_\_ Aerial \_\_\_\_\_ Onsite X

STRUCTURAL TYPE: Shelter Structure X River Community \_\_\_\_\_  
Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other \_\_\_\_\_

| WALLS:        | IN       | OUT      | FLOOR            | ROOF        | CORNER NOTCH     |
|---------------|----------|----------|------------------|-------------|------------------|
| Log-Rough     | _____    | _____    | Dirt             | Sod         | Unknown <u>X</u> |
| Log-Hewn      | _____    | _____    | Wood             | Metal       | _____            |
| Frame         | _____    | _____    | Other            | Wd. Plank   | _____            |
| Drop Siding   | _____    | _____    | Unknown <u>X</u> | Wd. Shingle | _____            |
| Wall Covering | _____    | _____    |                  | Tar Paper   | _____            |
| Unknown       | <u>X</u> | <u>X</u> |                  | Unknown     | <u>X</u>         |

TREATMENT RECOMMENDED: \_\_\_\_\_ ORDER OF SIGNIFICANCE: \_\_\_\_\_  
X LOCATE  
\_\_\_\_ Site Protection \_\_\_\_\_ National  
\_\_\_\_ Preservation/Stabilization \_\_\_\_\_ Regional  
\_\_\_\_ Restoration \_\_\_\_\_ Local  
\_\_\_\_ Reconstruction  
\_\_\_\_ Adaptive Reuse

Estimated Treatment Costs \_\_\_\_\_  
Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE \_\_\_\_\_ AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 \_\_\_ Difficult  
(Dog Sled, Snow Mach., Heli.)  
20  Medium  
(1 Day Hike, Boat, Fixed-Wing)  
40 \_\_\_ High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located  
1  No Remains  
3 \_\_\_ Ruin  
8 \_\_\_ Poor (Roof In)  
15 \_\_\_ Medium (Roof Intact)  
25 \_\_\_ Good (Maintained)  
40 \_\_\_ Restored

PRESENT VISITOR USE

- \_\_\_ Frequent  
 Infrequent  
\_\_\_ None

POTENTIAL VISITOR USE--20 POINTS

- 20 \_\_\_ High  
10 \_\_\_ Medium  
5  Low

Total Points 26

STATEMENT OF SIGNIFICANCE:

IPITAROD PIONEER OF 1910-11 IDENTIFIES A KATE MASTERS AS A PROPRIETOR OF THE WILLOW CR. ROADHOUSE, 1910

SOME STRUCTURES REMAIN AT THE SITE, HOWEVER NONE ARE BELIEVED TO BE OF THE HISTORICAL PERIOD OF THE IPITAROD.

REFERENCE:

SITE RECOMMENDATIONS: