

IDITAROD TRAIL INVENTORY

4/78
SITE JULY CREEK ARC CABIN AHRS NO: ZDT-027 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: 2/13/81
State Patented #50-76-0074

(MTP 9-2-76)

LEGAL DESCRIPTION:
Approximate Actual _____
Quad. ZDT C-3
Township 30 N
Range 40 W
Section 22
Subsection SE 1/4, NE 1/4

Latitude: 62° 39' 05"
Longitude: 157° 07' 10"

UTM REFERENCE: _____

A _____
Zone Easting Northing

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED: _____

ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 13

STATEMENT OF SIGNIFICANCE:

BUILT BY A.R.C. IN 1922 - consisted of a cabin with a (6) horse Barn.

REFERENCE:

SITE RECOMMENDATIONS: