

Iditarod National Historic Trail Office
Bureau of Land Management

General Work Sheet

Name of Site DALZELL R.H.	AHRS Number M-4-003	Site Number 220 A
------------------------------	------------------------	----------------------

Other Site Names or Location
DALZELL SHELTER

Land Status
STATE SELECTION (D-1 LAND) PENDING

UTM Coordinates (zone, easting, northing)	Title of USGS Quadrangle	Geographic Location
--	--------------------------	---------------------

Present Owner's Name and Address

Present Occupant
ABANDONED.

Present Use
ABANDONED RUIN

Brief Statement of Significance:
LOCATION: COMMANDING VIEW OF PASS CREEK (UP) AND DALZELL RIVER (UP & DOWN)

Project Information

Type of Inspection
On Site X JULY 9, 1980 Aerial _____

Name of Site	Site Number
--------------	-------------

PHYSICAL HISTORY

Dates of Erection
LIVELL GOODWIN

Architect

Original and Subsequent Owners

Builder or Contractor, Suppliers

Notes on Original Plan and Construction of Building

Notes on Known Alterations and Additions, with Dates and Architects

HISTORICAL EVENTS AND PERSONS ASSOCIATED WITH THE BUILDING

SOURCES OF INFORMATION

Primary and Unpublished Sources

Goopwml

Secondary and Published Sources

Likely Sources Not Yet Investigated

ORAL HISTORY, NIKIL DENNIS, NICHOLAI, HAS HUNTED AREA FOR 15 YEARS.

Prepared by

Stanton

Date of Visit

JULY 19, 80 11:30am.
Weather Conditions
CLOUDY - SPRINKLES

Iditarod National Historic Trail

Inventory Work Sheet

Site Name DALAZELL R.H.	AHRS Number MLG-003	Site Number 220-A
Trail Section RAINY PASS TO FAIRWELL LAKE	Distance From _____, _____ Miles or Flight Time	
Land Status		

Location	USGS Map Quad
----------	---------------

Longitude	Latitude
-----------	----------

LEGAL DESCRIPTION

Township	Range	Sec.	Sub.	Meridian
----------	-------	------	------	----------

Acreage

GENERAL DESCRIPTION

Architectural Merit and Interest

IDITAROD ROADHOUSE - COMMANDING VIEW

Condition of Fabric

RUIN.

DETAILED DESCRIPTION OF EXTERIOR


Overall Dimensions 46'10" x 17'10"	Number of Bays 3 BAYS	Number of Stories 1	Layout, Shape RECT. 
--	---------------------------------	-------------------------------	---

Foundations

LOG SILLS - DIRECTLY ON SOIL

Wall Construction, Finish and Color

LOG CONSTRUCTION



Structural System, Framing

LOG - - SADDLE NOTCHED - LOG END TRIMED TO WALL FACE
↑
(SAWN)

QUICKLY BUILT - NO NAILING EVIDENT, WINDOWS, DOORS NOTCHED.
↑
EXCEPT SUB CASING ON INSIDE.

Porches, Stoops, Bulkheads

NONE EVIDENT.


mneys

— UNKNOWN

Openings: Doorways and Doors

Windows and Shutters

UNKNOWN



Roof: Shape, Covering

UNKNOWN (ASSUMED GABLE END) (ROOF DOWN $\pm$ 10 YEARS)

Cornice, Eaves


UNKN

Dormers, Cupolas, Towers

UNKN

DETAILED DESCRIPTION OF INTERIOR

Floor Plans (by floors)



Stairways

NONE

Flooring

UNKNOWN (ASSUMED SLAB FLOOR ON LOG PURLINS (ON 4 ROUND).

Wall and Ceiling Finish

ROUGH ADDED LOG FACE, NO EVIDENCE OF CONCRETE

Doorways and Doors

Special Decorative Features, Trim and Cabinet Work

Notable Hardware


NONE

Mechanical Equipment (Heating, Lighting and Plumbing Systems and Fixtures of Note)

NONE

SITE AND SURROUNDINGS


General Setting (Including Orientation by Compass Reading)



Historic Landscape Design

TRAIL THROUGH SITE

Outbuildings



Site Use Recommendations

SHOULDER CABIN SITE (RECONSTRUCTION)

GREAT SCENIC QUALITIES.

PASS GREEN GLACIAL STREAM

STABILIZE EXISTING RUINS.



FEW ARTIFACT / HARDWARE

- 8" METAL STAMPED FRYING PAN

Proposed Site Preservation Program and Cost Estimate

STABILIZE RUINS

1. SUPPORT EXISTING WALLS
2. TREAT WOOD, WOOD PRESERVATIVES.



Prepared By

Date