

1 SITE RAINY PASS SHELTER CABIN

AHRS NO: ~~MCG-007~~ INHT NO. 220D

2 OTHER SITE NAMES:

- 3 1 RAINY PASS ROAD HOUSE
- 4 2 PASS CREEK ROADHOUSE

TRAIL SECTION:

- 1 SEWARD - RAINY PASS
- 2 RAINY PASS - KALTAH
- 3 KALTAH - NOME

9 LAND STATUS:

15 LEGAL DESCRIPTION:

16 APPROXIMATE  ACTUAL \_\_\_\_\_  
 17 QUAD. ANCHORAGE A-1  
 18 TOWNSHIP 24 N  
 19 RANGE 21 W  
 20 SECTION 11  
 21 SUBSECTION NWNWSE

22 LATITUDE: 62° 11' 40"  
 23 LONGITUDE: 153° 01' 00"

26 UTM REFERENCE:

27 A \_\_\_\_\_  
 28 ZONE EASTING NORTHING

29 LOCATION USE

33 INSPECTED BY: LYNCH (78) PETERSON (80) DATE: \_\_\_\_\_ AERIAL  ONSITE \_\_\_\_\_

35 STRUCTURAL TYPE: SHELTER STRUCTURE  RIVER COMMUNITY \_\_\_\_\_  
 36 NATIVE SETTLEMENT \_\_\_\_\_ MINING COMMUNITY \_\_\_\_\_ OTHER \_\_\_\_\_

37	38 WALLS:	39 IN	40 OUT	41 FLOOR	42 ROOF	43 CORNER NOTCH
39	LOG-ROUGH	---	---	DIRT	SOD	UNKNOWN <input checked="" type="checkbox"/>
40	LOG-HEWN	---	---	WOOD	METAL	
41	FRAME	---	---	OTHER	WD. PLANK	
42	DROP SIDING	---	---	UNKNOWN <input checked="" type="checkbox"/>	WD. SHINGLE	
43	WALL COVERING	---	---		TAR PAPER	
44	UNKNOWN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		UNKNOWN <input checked="" type="checkbox"/>	

45 TREATMENT RECOMMENDED

ORDER OF SIGNIFICANCE:

- |    |                                |   |
|----|--------------------------------|---|
| 47 | ___ PRESERVATION/STABILIZATION | ___ NATIONAL                              |
| 48 | ___ RESTORATION                | ___ REGIONAL                              |
| 49 | ___ RECONSTRUCTION             | <input checked="" type="checkbox"/> LOCAL |
| 50 | ___ ADAPTIVE REUSE             |   |

52 ESTIMATED TREATMENT COSTS \_\_\_\_\_

ESTIMATED PLANNING/RESEARCH COSTS \_\_\_\_\_

*LANICE*

SITE: RAINY PASS SHELTER CABIN. AHSR NO. McG-007 INHT NO. 220-D

MANAGEMENT RATING CRITERIA

ACCESS — 40 POINTS

- 5  DIFFICULT —  
(POG SLED, SNOWMOB, HELICOPTER)
- 20  MEDIUM —  
(1 DAY HIKE, BOAT, FIXED WING)
- 40  HIGH —  
(AUTO/ROAD, SHORT HIKE)

CONDITION — 40 POINTS

- NOT LOCATED
- 1  NO REMAINS
- 3  RUIN
- 8  POOR (ROOF IN)
- 15  MEDIUM (ROOF INTACT)
- 25  GOOD (MAINTAINED)
- 40  RESTORED

PHOTO

PRESENT VISITOR USE

- FREQUENT
- INFREQUENT
- NONE

POTENTIAL VISITOR USE — 20 POINTS

- 20  HIGH
- 10  MEDIUM
- 5  LOW

TOTAL POINTS 41

STATEMENT OF SIGNIFICANCE

STATEMENT OF SIGNIFICANCE — ~~LOCAL SIGNIF.~~  
 STRUCTURE SERVED AS AN EMERGENCY SHELTER FOR TRAVELERS OVER RAINY PASS FOR YEARS PRECEDING, DURING AND AFTER THE IDITAROD RUSH (1908-1930's). TRAVELERS (FROM THE EAST) WOULD IN THE 1920'S STOP AT THE CABIN AND TELEPHONE TO DALZELL CABIN TO VERIFY THE "PASS" CONDITION BEFORE TRAVELING ON. — "20 YEARS AS A SOLDIER OF FORTUNE". FLOYD R. MARSH, 1976

GOODWIN NOTES THE RELIEF CABIN IN HIS 1908 NOTES.  
 KROLL'S MAP - 1920  
 ALASKA-YUKON MAP. JULY 1911 - DISCUSSES GOODWIN'S 1910-11 TRAIL SURVEY

NATIONAL

SITE RECOMMENDATIONS:

1. POSSIBLE RECONSTRUCTION OF A ~~SHED~~ RELIEF CABIN IN ~~THE~~ SUPPORT OF RECREATIONAL & SURVIVAL USE.
2. LOCATE

REFERENCE ->