


- CABIN LOGS ARE HEWN FLAT ON THEIR INSIDE FACES,
MOST HAVE SAWN ENDS, FEATURE AT NW CORNER
MAY BE A DOOR, - WEST SIDE IS INDISTINGUISHABLE.



SULLIVAN R.N. SITE


SKETCH MAP OF SITE


(NOT TO SCALE)

SACCUAN R.N. SITE



7/5/78
BECK

Cache remains - Built of spruce logs cradle notched
on support posts 8-10" in diameter
probably extending 6-8' above the ground.
Round nails occur where used and tie
cons encircle tops of support posts 6"
below their tops. Logs have V cuts to support
cross posts. Wall logs average 6" in dia
at butt ends, alternated in walls as to
direction of butt ends. Logs are mostly cut
almost no beaving. Support posts sawn on base ends,
indicating they were short only approx 90" long.
Evidence of lateral props may indicate cache
was not very stable. Floor was made of boards 1" x 8 or 9"
nailed together w/ Z bracing of 1x4's. Roof const.
is unknown. Boards in roof may indicate lumber
roof (possibly ship-lapped?). Well log of doorway is
approx 30-31" cut out for bottom of door.
Doorway, faced trail, to the west, fronting almost
right upon it.





Strong hinge on 40" board indicates was upright on long dimension



FRONT SIDE OF DOOR

SULLIVAN R.H. SIVE

7/6/78
BECK

- VICTOR SPRING TRAP W/ 5" JAWS FROM CACNE AREA
- ALSO A FIFTH W/ "FEDERAL LAW FORBIDS SALE OR REUSE"

SKETCH PLAN OF CABIN

