OTHER CITE NAMEC.	TO ATT CECTTON.	H
OTHER SITE NAMES:	TRAIL SECTION: Seward-Rainy Pass	
	Rainy Pass-Kaltag X	tang pangangan
	Kaltag-Nome	
	and the second of the second	
LAND STATUS:		ا ا
		ENTOB
		P.T
LEGAL DESCRIPTION:		
Approximate ⊀ Actual		> Z
Quad. NVL		
Township T135		
Range <u>El</u> E Section 290230		
Section <u>290230</u> Subsection		
Latitude: <u>64º 19' 45"</u>		_
Longitude: 158° 43' 06"		
WAY DEFENDANCE		
UTM REFERENCE:		AI
Zone Easting	Northing — — —	KT:
LOCATION AND USE:	notening	
IN. KILTAG - STORE AWD RODON		<u>~</u>
Manual - Store and Robbits	20 G	
INSPECTED BY: Petron	DATE: Jun 80 Aerial Ons	ideo X
INSPECTED BI: Flettung	DATE. OUR SO REITAI OUR	Tie /
STRUCTURAL TYPE: Shelter Str	ucture 人 River Community	
Native Settlement Min	ing Community Other	
	· .	
WALLS: IN OUT FLOO		ER NOTCH
Log-Rough Di Log-Hewn Wo		known <u>k</u>
	her Wd. Plank	G
	known Y Wd. Shingle	
Wall Covering	Tar Paper	K
Unknown x x	Unknown $\sqrt{}$	~
TREATMENT RECOMMENDED:	ORDER OF SIGNIFICANCE:	 ITA
Site Protection	National	·
Preservation/Stabilizati		
Restoration	Local	
Reconstruction		
Adaptive Reuse		
Waster-Agents.		
Estimated Treatment Costs	Paral Der and Angelia principle programs	
Estimated Planning/Research C	osts	

SITE	AHRS NO:	INHT NO:
MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS	•	
5 Difficult	•	
(Dog Sled, Snow Mach., Heli.)		
20 X Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 ¥ High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located	•	
l x No Remains		
3Ruin		
8 Poor (Roof In)		
15 Medium (Roof Intact)		
25 Good (Maintained)		
40Restored		
PRESENT VISITOR USE		
x Frequent		
Infrequent		
None		
POTENTIAL VISITOR USE20 POINTS		
20High		
10Medium		
5_x_Low		
7/		
Total Points Z6		

STATEMENT OF SIGNIFICANCE:

THE MULLER' ROADHOUSE AND STORE DO NOT REMAIN TODAY.

SERVED AS A R. H. FOR TRAVELORS ON THE YULGON AND CHER THE KALTAG

PORTAGE.

REFERENCE:

PETEGONAL COMMA - EDGAR KALDAND, KALTAG, JUNE 1980.

SITE RECOMMENDATIONS: