

SITE BOOB CREEK MINING AREA AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

OTHER SITE NAMES: \_\_\_\_\_

TRAIL SECTION:

Seward-Rainy Pass \_\_\_\_\_  
Rainy Pass-Kaltag X \_\_\_\_\_  
Kaltag-Nome \_\_\_\_\_

LAND STATUS: \_\_\_\_\_

LEGAL DESCRIPTION:

Approximate \_\_\_\_\_ Actual X  
Quad. DPH  
Township T25S  
Range R10E  
Section 8  
Subsection SW 1/4, SE 1/4, SW 1/4

Latitude: 3° 19' 50"  
Longitude: 107° 00' 9.26"

UTM REFERENCE:

A \_\_\_\_\_  
Zone \_\_\_\_\_ Easting \_\_\_\_\_ Northing \_\_\_\_\_

LOCATION AND USE:

2 MILES UP BOOB CREEK FROM ITS CONFLUENCE WITH MASTOPON CREEK.

INSPECTED BY: PETERSON DATE: JUNE 80 Aerial \_\_\_\_\_ Onsite X

STRUCTURAL TYPE: Shelter Structure \_\_\_\_\_ River Community \_\_\_\_\_  
Native Settlement \_\_\_\_\_ Mining Community X Other \_\_\_\_\_

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	<u>X</u>	<u>X</u>	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood <u>X</u> _____	Metal _____	<u>SADDLE NOTCH</u>
Frame	_____	_____	Other _____	Wd. Plank <u>X</u> _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper <u>X</u> _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED: \_\_\_\_\_ ORDER OF SIGNIFICANCE: \_\_\_\_\_

- \_\_\_\_\_ Site Protection
- \_\_\_\_\_ Preservation/Stabilization
- \_\_\_\_\_ Restoration
- \_\_\_\_\_ Reconstruction
- \_\_\_\_\_ Adaptive Reuse
- \_\_\_\_\_ National
- X \_\_\_\_\_ Regional
- \_\_\_\_\_ Local

X Return  
Estimated Treatment Costs \_\_\_\_\_  
Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE \_\_\_\_\_ AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5  Difficult  
(Dog Sled, Snow Mach., Heli.)  
20  Medium  
(1 Day Hike, Boat, Fixed-Wing)  
40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located  
1  No Remains  
3  Ruin  
8  Poor (Roof In)  
15  Medium (Roof Intact)  
25  Good (Maintained)  
40  Restored

PRESENT VISITOR USE

- Frequent  
 Infrequent  
 None

POTENTIAL VISITOR USE--20 POINTS

- 20  High  
10  Medium  
5  Low

Total Points 18

STATEMENT OF SIGNIFICANCE:

HISTORIC PLAGIER MINING CLAIM, SMALL. REPORTED TO HAVE BE LOCATED AND WORKED BY DEL-THOMPSON THOMSON. ACTIVE MINING ONGOING IN 1980.

THE REMAINS AT 13003 GR. THE RUINS OF 6 STRUCTURES RANGING IN CONDITION FROM RUIN TO POOR STANDING CONDITION.

REFERENCE:

SITE RECOMMENDATIONS: