

SITE RENNIE'S LANDING

AHRS NO: OPH-022 INHT NO: \_\_\_\_\_

OTHER SITE NAMES: \_\_\_\_\_

TRAIL SECTION:  
Seward-Rainy Pass   
Rainy Pass-Kaltag \_\_\_\_\_  
Kaltag-Nome \_\_\_\_\_

LAND STATUS: \_\_\_\_\_

LEGAL DESCRIPTION:

Approximate \_\_\_\_\_ Actual   
Quad. OPH  
Township T 22 S  
Range R 9 E  
Section 2  
Subsection NW 1/4, SE 1/4, SE 1/4  
Latitude: 63° 36' 30"  
Longitude: 157° 12' 45"

UTM REFERENCE:

A \_\_\_\_\_  
Zone \_\_\_\_\_ Easting \_\_\_\_\_ Northing \_\_\_\_\_

LOCATION AND USE:

INSPECTED BY: \_\_\_\_\_ DATE: \_\_\_\_\_ Aerial \_\_\_\_\_ Onsite \_\_\_\_\_

STRUCTURAL TYPE: Shelter Structure \_\_\_\_\_ River Community   
Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other \_\_\_\_\_

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <input checked="" type="checkbox"/>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <input checked="" type="checkbox"/>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		Unknown	<input checked="" type="checkbox"/>

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- |                                  |   |
|----------------------------------|---|
| _____ Site Protection            | _____ National                            |
| _____ Preservation/Stabilization | _____ Regional                            |
| _____ Restoration                | <input checked="" type="checkbox"/> Local |
| _____ Reconstruction             |   |
| _____ Adaptive Reuse             |   |

Estimated Treatment Costs \_\_\_\_\_  
Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE \_\_\_\_\_ AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5  Difficult  
(Dog Sled, Snow Mach., Heli.)  
20  Medium  
(1 Day Hike, Boat, Fixed-Wing)  
40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located  
1  No Remains  
3  Ruin  
8  Poor (Roof In)  
15  Medium (Roof Intact)  
25  Good (Maintained)  
40  Restored

PRESENT VISITOR USE

- Frequent  
 Infrequent  
 None

POTENTIAL VISITOR USE--20 POINTS

- 20  High  
10  Medium  
5  Low

Total Points 10

STATEMENT OF SIGNIFICANCE:

UNKNOWN - QUESTION AS TO THE LOCATION OF COOPER'S ROAD HOUSE,  
WAS LOCATED EITHER AT TOLSTOI OR BUNNIEZ LANDING.

ED. CUTLER, WASICWA PASS INFORMANT ON BUNNIEZ LANDING

REFERENCE:

USGS MAP 1954

SITE RECOMMENDATIONS: