

SITE TWENTY MILE RIVER SAWMILL AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass X
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate X Actual _____
Quad. SEW D-6
Township T 9N
Range R 3E
Section 19
Subsection SE 1/4

Latitude: 60° 51' 00"
Longitude: 149° 58' 20"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 53

STATEMENT OF SIGNIFICANCE:

REFERENCE:

CARMENY, MICHAEL, E., PATTERNS OF THE PAST, ARCH/PLANNING COMM, JAN 1979

SITE RECOMMENDATIONS:

INTERP - MANUF OF F.B. TIES.