

SITE FALLS CREEK CONESTOGA SWAMP AHRS NO: SE10 XXX INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. _____
Township _____
Range _____
Section _____
Subsection _____

Latitude: _____
Longitude: _____

UTM REFERENCE:

A _____
Zone Easting Northing

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown _____
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 ___ No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 ___ Medium
- 5 ___ Low

Total Points 60

STATEMENT OF SIGNIFICANCE:

Const of the trail for guidance to Anchorage.

REFERENCE:

SITE RECOMMENDATIONS:

Locate, Clear, interpret

SITE FALLS CREEK CABINS AHRS NO: SEW-113 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 4/7/81 pm
R/W RR; CLASSIF;
HE; R/W PAIR; MULT USE
REG SEL

SEE SEW-018
FOR ADP PRINTOUT

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. SEW D-7
Township 10N
Range 2W
Section 2
Subsection NWSE

Latitude: 60° 59' 9"
Longitude: 149° 39' 38"

UTM REFERENCE:

A _____
Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
1 ___ No Remains
3 ___ Ruin
8 Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
 Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 Medium
5 ___ Low

Total Points 50

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: