

SITE BIRD STATION (R.R.) AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
Seward-Rainy Pass X
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. CEW
Township 10N
Range 1W
Section 24
Subsection SE NE

Latitude: 60°-56'-35"
Longitude: 149°-22'-30"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

BETWEEN BIRD CR & BIRD POINT MILE 81.7 (22 MILES)

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other RAILROAD STATION

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 Medium
- 5 ___ Low

Total Points 31

STATEMENT OF SIGNIFICANCE:

REFERENCE:

ABC, JUNE 27, 1921, MILE 8.7.

SITE RECOMMENDATIONS:

IDITAROD TRAIL INVENTORY

SITE CRBEK ~~BLD POINT~~ AHRS NO: SEW-125 INHT NO: _____

OTHER SITE NAMES: _____ TRAIL SECTION:
 Seward-Rainy Pass _____
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____

LAND STATUS: ADP 4/7/81 pm
 NATL FOREST; REG SEL
 U/D APLN; CLASSIF; R/W PWR
 MULT USE; ST GNT;

THIS ADP PRINTOUT
 ALSO APPLIES TO
 SEW-126
 SEW-132

LEGAL DESCRIPTION:

SEW-7
 1
 Approximate Actual
 Quad. SEW D-7
 Township 10 N
 Range 1 W
 Section 30 9
 Subsection SW 1/4 NW

Hope

SEWARD
 T 10N
 R 1W
 9
 NW

Latitude: 60° 55' 50"
 Longitude: 149° 21' 30" } Wrong

60° 13' 20"
149° 26' 30"

UTM REFERENCE:

A _____
 Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- ___ Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 ___ Low

Total Points _____

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: