

SITE SALOMON-COUNCIL CITY RR AHRS NO: SOL-032 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: 4/7/81 pm

D1, D2 W/D; VIL SEL;
NATIVE GROUP SEL
REINDEER GRAZE

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. C5
Township 11S
Range 29W
Section 11
Subsection NE

Latitude: 64° 33' 00"
Longitude: 164° 25' 00"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

_____ Site Protection	_____ National
_____ Preservation/Stabilization	_____ Regional
_____ Restoration	_____ Local
_____ Reconstruction	
_____ Adaptive Reuse	

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDENTIFIED TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
1 ___ No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- Frequent
___ Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 ___ Medium
5 ___ Low

Total Points 75

STATEMENT OF SIGNIFICANCE:

R.R. LOCOMOTIVES, REMAINS, RR. BEFORE IDITAROD

REFERENCE:

SITE RECOMMENDATIONS: